


DIGIMAT - QMS WIRING DIAGRAM



Note: One power supply is used for each five counters.

